



NOTES:

- 180° F (82° C) MAXIMUM TEMPERATURE.
- PRIOR TO INSTALLING POURABLE SEALER POCKET AND UNCURED FLASHING TAPE, PRIME MEMBRANE AND POURABLE SEALER POCKET WITH MULE-HIDE TAPE PRIMER AND ALLOW TO PROPERLY DRY.
- POURABLE SEALER MUST CONTACT UNCURED FLASHING AND DECK MEMBRANE.
- POURABLE SEALER POCKET TO BE 1" (3 cm) MINIMUM FROM PENETRATION ON ANY SIDE.
- POURABLE SEALER MUST COMPLETELY FILL POURABLE SEALER POCKET TO PREVENT PONDING OF WATER.
- SECUREMENT IS REQUIRED FOR POURABLE SEALER POCKETS WHICH ARE GREATER THAN 18" (50 cm) IN DIAMETER. REFER TO SPECIFICATIONS.
- POURABLE SEALER TO BE MINIMUM 2" (5 cm) DEEP.
- POURABLE SEALER MUST CONTACT THE BARE SURFACE OF THE PENETRATION. ALL DEBRIS (PAINT, RUST, LEAD, OTHER FLASHINGS, ETC.) MUST BE REMOVED FROM THE PENETRATION.
- FOR ADDITIONAL INFORMATION, REFER TO MULE-HIDE POURABLE SEALER POCKET INSTALLATION INSTRUCTIONS IN THE EPDM SECTION.

**MULE-HIDE  
PRODUCTS CO., INC.  
2005**

Pourable Sealer Pocket  
Double Application

SYSTEMS:  
Fully Adhered 90mil System

DETAIL NO.:  
**MHE-518**