



NOTES:

1. THE MAXIMUM ALLOWABLE SURFACE TEMPERATURE OF THE PENETRATION SHALL NOT EXCEED 180° F (82° C).
2. ALL DEBRIS (PAINT, RUST, LEAD, OTHER FLASHINGS, ETC.) MUST BE REMOVED FROM THE PENETRATION.
3. PENETRATIONS, MEMBRANE, FLASHING AND METAL (INSIDE POCKET) MUST BE PRIMED WITH EPDM PRIMER PRIOR TO APPLYING POURABLE SEALER. DO NOT PRIME THE BLUE PLASTIC SUPPORT STRIP.
4. POURABLE SEALER MUST COMPLETELY FILL POURABLE SEALER POCKET TO PREVENT PONDING OF WATER.
5. POURABLE SEALER MUST CONTACT PRIMED UNCURED FLASHING TAPE AND DECK MEMBRANE.
6. ON MECHANICALLY FASTENED SYSTEMS, INSTALL A MINIMUM OF FOUR (4) 2.4" SEAM PLATES AROUND SEALANT POCKETS WITH DIAMETERS OVER 12".
7. FASTENERS AND SEAM PLATES ARE NOT REQUIRED ON ADHERED SYSTEMS UNLESS SEALANT POCKET DIAMETER EXCEEDS 12".
8. PIPE CLUSTERS MUST HAVE MINIMUM 1" CLEARANCE BETWEEN PENETRATIONS.

**MULE-HIDE
PRODUCTS CO., INC.**

**WHITE EPDM
PREFABRICATED SEALANT POCKET
SYSTEMS:
ALL TPO SYSTEMS**

DETAIL NO.:
MHT-UN-527A
REVISION DATE: 06/2017