


NOTES:

1. Cleaning and Preparation - Clean and prepare the surface by brooming mild detergent & water rinse or as required to remove any conditions that could adversely affect the adhesion of primers and liquid materials.
2. Surface to receive Polyglass Liquid Flashing System may need to be primed, depending on the surface.
3. For Polyester Reinforcement Cutout and Application instructions, refer to Reinforcement Details.
4. Illustration and notations intended for generalized application only. Please refer to Product Data Sheets for additional information.



APPLICABLE SYSTEMS (AND MEMBRANES)

**MULEHIDE**

PIPE PENETRATION LIQUID FLASHING DETAIL

**DETAIL NO.:**

**MB-PP-A302**

MAXIMUM WARRANTY:  
20 YEARS MAX

REVISION DATE: 6/8/2026